## ⚠ Before You Start

A Tapo Hub is required. Make sure your Tapo Hub is successfully added via the Tapo app.


1 Power Up Your Sensor

Remove the battery insulation tab to power up your sensor. The LED should blink.

Note: If the LED is not blinking, refer to the reverse side for reset instructions.


2 Set Up Your Sensor

Open the Tapo app and tap the ⊕ button. Select **Sensors** and then your model. Follow the app instructions to complete setup.


3 Test Your Sensor

Take your sensor to the preferred location and wave your hand in front of the sensor to test it. The Tapo app should show if the sensor is triggered.


4 Place Your Sensor

Option 1:
Magnetically attach to metallic objects

Metallic Object

OR

Option 2:
Stick to a clean wall with included adhesive

Adhesive

OR

Option 3:
Place it on a shelf or table

⚠ Detection Area

The sensor should be aligned with the detection area and placed as close as possible to the edge of a table or cabinet. The installation height should not be higher than 2 meters.

2m

1m 5m 7m

Side View

120°

1m 5m 7m

Top View

Meet Your Motion Sensor

The Motion Sensor detects movement in a certain area and triggers different actions in response. This makes your home safer and smarter.


Sensor Detector
LED
Cover
Mounting Stand
Reset
Reset Button
+ CR2450
Battery Compartment

How to replace the battery

| Option 1: With a Shim	Option 2: By Hand

1 2
OR
3 4

+ CR2450

1 2
3 4

+ CR2450

How to reset your sensor

Use a pin to press and hold the Reset button for 5 seconds until the front LED starts blinking.

5s

?

Need some help?

Visit www.tapo.com/support/
for technical support, user guides,
FAQs, warranty & more

UK CA EAC FC C€ ✓

For EU/UK Region:
Operating Frequency / Nominal Operating Frequency / Max Output Power:
863~865MHz / 863.35MHz / 25mW (e.r.p)
863~865MHz / 864.35MHz / 25mW (e.r.p)
868~868.6MHz / 868.35MHz / 25mW (e.r.p)

tp-link | tapo

Quick Start Guide
Smart Motion Sensor

▶ Setup Video

Scan QR code or visit
https://www.tp-link.com/support/
setup-video/#smart-sensors